

NEWS > COLORADO NEWS

Deadly Firestone explosion caused by odorless gas leaking from cut gas flow pipeline

Governor orders inspection of all oil and gas lines within 1,000 feet of occupied homes

By **BRUCE FINLEY** | bfinley@denverpost.com | The Denver Post PUBLISHED: May 2, 2017 at 2:51 p.m. | UPDATED: May 3, 2017 at 9:24 a.m.

0

FIRESTONE – A fatal house explosion was caused by odorless gas seeping from a cut-off underground pipeline into the house through French drains and a sump pit, Frederick-Firestone Fire Protection District chief Ted Poszywak said.

Fire investigators found a 1-inch diameter black plastic pipeline running from an Anadarko Petroleum well near the house that had been cut when a tank battery was moved before the Oak Meadows subdivision was built, Poszywak said. That pipeline leaked the gas from a point 6 feet from the southeast corner of the house at 6312 Twilight Ave. in Firestone. Investigators said they found the gas valve at the Anadarko well in the "on" position.

Poszywak said leaking gas "saturated the soil and migrated into the French drains of the home."

Soon after the firefighters released their report Tuesday, Gov. John Hickenlooper ordered oil and gas companies statewide to inspect and pressure-test oil and gas flowlines within 1,000 feet of occupied buildings.

Hickenlooper said companies must make sure flowlines not in use are properly marked and capped, and that any abandoned flowline cut off underground is sealed.



6/28/2021 Case 4:20-cvaluato Floestoria acquisitionatus 807 b 2 odories legis obsailuta / 120 jas Tows Deline Parageo 2 norte 60st



R) Sangosti. The Deriver Post. A gas well, on the left, covered by tan fencing is less than 200 feet from a home where crews continue to investigate a fatal house explosion on April 27, 2017 in Firestone.

Frederick investigators found "prerefined gas" — gas that had not been odorized for safety — in the basement sump pit and French drains, Poszywak said. "Those inside the home would not have smelled it."

The gas was a volatile mix of methane and propane, he said. It "found an ignition source inside the home. It erupted into a sudden and violent explosion" that killed homeowner Mark Martinez and his brother-in-law Joey Irwin and critically injured Martinez's wife, Erin.

Family members have said Martinez and Irwin were working on a water heater in the basement of the house.

The Anadarko Petroleum oil and gas well sits 178 feet from the house that burned and collapsed in the fiery explosion April 17. Colorado Oil and Gas Conservation Commission regulators announced last week they were supporting the local firefighters' investigation, and Anadarko officials said they voluntarily were shutting down 3,000 of their older, vertical oil and gas wells in northeastern Colorado as a precaution.

"It was the pipeline rather than the wellhead that caused the buildup related to the explosion," Poszywak said.

Anadarko had left the well dormant in 2016 and restarted it in January. Anadarko operators may not have pressure-tested underground flow lines to detect leaks, one of many issues the COGCC regulators said they would review.

COGCC chief Matt Lepore said Tuesday afternoon that the commission will consider adopting new rules to require pressure testing for smaller flow pipelines. He added that rules regarding mapping of pipelines throughout the state also will be reviewed as well as other matters.

The house explosion on Twilight Avenue has re-ignited concerns about oil and gas industry operations close to where people live along Colorado's booming Front Range.

While the COGCC requires companies drilling new oil and gas wells to stay 500 feet from homes (unless companies make deals with landowners and get special permission), state officials leave it to local governments to determine how close to industry facilities new houses can be built.

Firestone's municipal code allows new house construction as close as 150 feet to existing oil and gas facilities.

"We do not have any definitive answer for what happened," Oak Meadows subdivision builder Century Communities spokesman Andy Boian said. "We are 100 percent committed to finding out what happened."

Andy Cross, The Denver Post
A Frederick/Firestone firefighter rolls up a hose in front of the remains of a home on the 6300 block of Twilight Ave. in Firestone, Tuesday morning
April 18, 2017

Environment and public safety groups this week were focused on the issue of underground industry pipelines that carry oil and gas away from wells — like the one that leaked gas into the Martinez family home.

State Sen. Matt Jones, a Boulder County Democrat, on Tuesday warned of "a recipe for disaster that could cause people to get hurt."



6/28/2021

D21 Case 4:20-chedid576stonfboologiquatise8742dorless/god/less/god/less/god/foot/speine-Fbobery-offost

"As more information has come to light, it has become clearer that these oil wells, pipes, and tanks are simply too dangerous to be in close proximity to homes, businesses, and schools," Jones said. "We need to take steps to ensure a tragedy like this doesn't happen again."

The Sierra Club is urging state leaders to stop permitting new oil and gas operations until the COGCC overhauls its current process to make sure public health and safety and the environment are protected.

Pointing to the recent Colorado Court of Appeals ruling that oil and gas production can only be done if it does not hurt people and the environment, Sierra Club "Beyond Oil and Gas" campaign director Harv Teitelbaum said COGCC regulators too often waive rules and approve projects "in service of drilling operator convenience and economic expediency

"As a result of these loopholes and rubber-stamped waivers, homeowners and prospective buyers in newer housing developments are not adequately informed of the potentially fatal risks they face," he said.

Sierra Club members "are very concerned about this, and suspect that this is not an isolated situation," Teitelbaum said. "Even if not right on top, corrosion in nearby lines, combined with various pathways for gas migration, present a serious, ongoing, widespread risk. ... All operators in Colorado should be required to immediately suspend operations at similar wells, fully inspect and report on those wells — not on a voluntary basis — with monitoring systems put in place to alert authorities to any leaks. Long-term, this problem will only get worse as corrosion, geologic action and age affect the integrity of all old wells."

Popular in the Community

AdChoices

Sponsored

Policies Report an Error Contact Us Submit a News Tip

The Trust Project

TAGS: ANADARKO PETROLEUM, FIRESTONE EXPLOSION, OIL AND GAS

Bruce Finley | Environment Reporter

Bruce Finley covers environment issues, the land air and water struggles shaping Colorado and the West. Finley grew up in Colorado, graduated from Stanford, then earned masters degrees in international relations as a Fulbright scholar in Britain and in journalism at Northwestern. He is also a lawyer and previously handled international news with on-site reporting in 40 countries.

bfinley@denverpost.com

Follow Bruce Finley @finleybruce

0

SPONSORED CONTENT

Don't Leave Shore Without It -

By Boat California



6/28/2021 Case 4:20-cvbQQb, Frestor Porphysitant La887 by Podor Filed squark 15/2011/25 jbs Tox Speline Pages 4 not post





Make your love for boating official. Apply for your California Boater Card today. Click here to learn how.

6/28/2021